

S E C R E T

25X1

25X1

25X1

25X1

25X1 25X1

SOBJECI:	си меекту кер	ort - 22 0c	1984		
е.	Renovatio	ons:			
₩ 50% of aprons 1984.	1) Repaving the work of . Remainder 2) Bulle. Estimate	installing of the work	a blacktop should be	slurry seal accomplishe	on driveway ed 26 Octobe
servic Instal outsta	3) OC/Repair e upper deck lation to be nding item on	and Return of this fac accomplishen the comple	Facility: ility was d shortly. te renovat	The electr finally rece This was t ion of this	ric lift to eived. The only facility.
					i